

Eberle Design Inc. 3819 East La Salle Street Phoenix, AZ 85040

Telephone	480-968-6407
Fax	602-437-1996
e-mail	support@editraffic.com
web site	www.editraffic.com

Scott Evans	Engineering Manager
Noel Soriano	Senior Design Engineer
Jon Muilenberg	National Sales Manager

2010ECL series Overview

- The signal monitor has three important tasks to perform:
 - » Detect improper signals / voltages
 - » *Display* cabinet status and fault status
 - » Diagnose with accurate information
- The EDI 2010ECL signal monitor brings state-of-the-art advancements to all 3 tasks

The EDI model 210ECL and 2010ECL have been completely redesigned using state-of-the-art technology which vastly improves performance and increases capabilities for the three main tasks of the signal monitor.

Reliable detection of signals has traditionally been adversely affected by changes in phase and frequency, as well as sine wave distortion. The 2010ECL uses a high speed coprocessor to measure the true RMS voltage and provide reliable detection in the on-street environment.

The front panel display has been improved to show full intersection status using Red, Yellow, and Green LEDs for each channel.

A full complement of event logging capabilities as well as the signal Trace History display helps present and document accurate status information about the events occurring at the intersection. This information is vital to the technician in repairing a cabinet malfunction and ensuring that the repair corrected the real cause of the malfunction.

Because of the high costs of malfunction maintenance calls and the increased exposure to liability, trouble shooting exercises must be done quickly and effectively. Traffic is not moving efficiently while the intersection is in flash.

2010ECL series Overview Enhanced Caltrans 210 monitor Exceeds all Caltrans TSCE 1989 requirements Adds Red Monitoring, Dual Indication Monitoring, Sequence (Clearance) Monitoring RMS-Enginetm DSP Coprocessor Full RYG Intersection Display Eccomtm Windows based software Went Logging & Signal Sequence Log

Enhanced Caltrans 210 Monitor

The 2010ECL monitor is built on the basic Caltrans 210 platform. Enhancements have been made to provide a broader fault coverage including Red Monitoring, Dual Indication Monitoring, and Sequence (Clearance) monitoring.

EDI RMS-Engine DSP Coprocessor

The EDI RMS-Engine is a high speed coprocessor that controls the analog to digital circuitry and processes the resulting sampled data using digital signal processor (DSP) techniques. These algorithms produce a result which is the true Root Mean Square (RMS) voltage of the AC input. A second microprocessor then uses the RMS signal voltages to determine fault status and perform monitor operational functions.

Full RYG Intersection Display

The full intersection display shows the status of all field inputs simultaneously. Improper signal displays are instantly recognizable.

Eccom Software

The EDI ECcom software is used to display the detailed data in the monitor event logs and examine the monitor configuration. These logs document the exact status of fault events and AC Line events to assist in diagnosing intermittent or transient problems.



The 2010ECL is based on a dual microprocessor architecture. The RMS-Engine coprocessor is dedicated to calculating true RMS analog AC input voltages.

Traditional monitors use a threshold technique which is sensitive to changes in phase, frequency, and wave form distortion. These sensitivities can shift the threshold of detection or produce erroneous results in a noisy environment such as electrical storms, ac line instabilities, etc.

The over sampling technique used in the EDI RMS-Engine produces the correct RMS voltage value regardless of the wave form. It works accurately for ac, dc, sine, triangle, distorted ac, etc. Frequency shifts experienced during power line instabilities no longer can cause detection problems.

As a diagnosis tool, the actual voltage value rather than just the On/Off status of a signal gives one more piece of information needed to home in on the actual cause of a malfunction.



One of the first tasks of trouble shooting a cabinet is to compare the expected controller outputs to what the signal monitor sensed at the time of the fault. This helps isolate the problem down to the field, the load bay, or the controller.

The full intersection display of the 2010ECL shows the actual signal status for the Red, Yellow, and Green inputs to each channel simultaneously. Improper signal displays are instantly recognizable.

This makes the comparison to the load switch input status easy. The 2010ECL display also shows which channels were involved in the fault if triggered.

A simple diagnostic mode provides a look at the signal status for two previous faults without the need to hook up a PC to retrieve event logs. This can be a handy tool if the fault has been reset and a quick review is needed to verify previous events.

ECcom software will present the complete picture if a more detailed view is required.



It is important to use the tools available to the technician to find the cause of a malfunctioning cabinet quickly, and then repair the problem with a high level of confidence that the true cause was found. Call-backs for repeated problems only multiply the effect of the problem. Besides being a source of detailed and accurate information about the state of the intersection at the time of the fault, the event logs can also help provide accurate documentation about the malfunction.

Four Event Log Types (100 records total)

The Previous Failure log contains a record of the field signal voltages, control signal voltages, and cabinet temperature, all time-stamped with the time and date of the event.

The Monitor Reset log time-stamps when the intersection was cleared from the fault flash by a monitor reset. The entry to flash and exit from flash are now documented.

The AC Line log records any event on the AC Line which causes the monitor to transfer to flashing operation (power-down, short interrupt, or brownout), and records the actual line voltage. This helps in trouble shooting intermittent cabinet problems related to power service problems.

The Configuration Change log records any change to the monitor programming including the diode matrix, switches, or jumper selections.

All events are then sorted according to time and date to view them in the real time line they occurred.



Ever wonder what the signals did prior to a fault?

Did the controller execute an improper sequence to get a clearance problem or did a field malfunction cause it?

The Signal Sequence History feature of the 2010ECL will show all field signal states graphically for as much as 30 seconds prior to the monitor trigger point with 50 millisecond resolution.

This information is critical to diagnose signal sequence faults and intermittent flickering or blinking of field signals resulting in faults.



Configuration Change Monitoring

The 2010ECL maintains an internally calculated CRC value of the current configuration settings. These settings include the permissive diode matrix, SSM switches, Yellow Disable switches, Option switches and jumpers, and the Watchdog Enable switch. On power-up, reset, and periodically during operation, the unit will compare the current configuration settings with the previously stored value. If the settings have changed, the unit will automatically log the new setting. If the Configuration Fault option (SEL3) is selected, the 2010ECL will enter the fault mode.

This function guards against accidental changes in programming as well as any hardware failures which may cause a change in programming such as a program card diode or connector failure. The CRC value is displayed by ECcom and can be compared to a known configuration for each cabinet installation during periodic maintenance to ensure original intended programming is still present.

Red Cable Monitoring

The 2010ECL can be programmed to remain in flash if the Red Interface cable is not installed. This prevents enhanced functions (Red Fail, Dual Indication, and Sequence) from being disabled because the cable was removed or failed.

Cabinet Temperature

The 2010ECL will record and report the temperature of the cabinet in the real time mode and in fault event records. Overheating is a major cause of load switch failure and may indicate additional cooling or maintenance is required.



The power-up and low AC Line brownout specification has been modified in the 2010ECL to accomplish three goals whether in a 170 or 2070 based cabinet:

a) A guaranteed minimum flash time on power-up, brownout restore, and short AC Line interrupts to allow the 2070 CU time to boot and set signal outputs. This operation also mimics the NEMA minimum flash operation. NEMA and Type 170 intersections in close proximity will respond in similar fashion to the same AC Line condition.

b) The elevated brownout threshold (98 V) ensures that the monitor places the intersection in flash before the 170 or 2070 CU goes into the reset state (dark) at 92 V. This resolves the problem of the monitor detecting a Red Fail under low line condition because the thresholds of a Caltrans 170 and an enhanced monitor were too close.

c) Many Flash Transfer Relays (FTR) will not pull-in below 93-95 volts. The 98 V dropout of the 2010ECL ensures that the FTRs will be pulled-in to provide flash for a drooping AC Line. The 98 volt dropout also eliminates the need to disable CU Watchdog monitoring (Caltrans WDD) or Red Monitoring while the signals are still operating (I.e. 92V < AC Line <98V)



The Recurrent Pulse detection (RP DETECT) function is designed to respond to fault conditions which are intermittent in nature and do not meet the continuous timing requirements of the normal detection algorithms, yet may still produce improper signal displays. These input conditions are differentiated by their longer time constant and fault response times.

The figure shows an example of a recurrent Conflict fault. Channel 2 Green is detected active due to a malfunction of the load switch which caused the output to "flicker" On for 100 ms approximately every 200 ms. Since normal Conflict detection requires a continuous fault of at least 350 ms typical, this event could go undetected. The Recurrent Pulse detection algorithm will combine these pulses into one event and trigger a Conflict fault once the longer recurrent timing threshold is exceeded.

<section-header>EDI 2010ECLSetting the Standard
for
Quality and ReliabilityEberle Design Inc.

Thank you for using Eberle Design products.

Our goal is to provide you with the highest reliability, performance, and customer satisfaction possible.

Your inputs and comments are highly appreciated.