

MODEL 210C-OR

RMS Signal Monitor Operations Manual

Addendum to the 210C Operations Manual Firmware Version 16C11xx

1) CU Watchdog Fault

Modify Section 1.1.3 to read:

If the WDT Error fault mode is reset from a loss of AC power, the WDT Error LED will NOT remain illuminated to indicate a WDT Error existed but was cleared by the power loss. A Reset command is therefore NOT required to clear the LED fault indication.

EBERLE DESIGN INC.

3510 East Atlanta Avenue Tel (480) 968-6407
Phoenix, AZ 85040 USA Fax (602) 437-1996
www.EDIttraffic.com



